

HOBBS OCD

JUN 17 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP		API Number 30-025-02091
Property Name Vacuum Glorieta West Unit		Well No 7

Surface Location

U/L - Lot N	Section 24	Township 17S	Range 34E	Feet from 660	N/S Line S	Feet From 1980	E/W Line W	County Lea
----------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------


Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER OIL ☒ GAS ☐	DATE 4/10/19
--	--	---	--	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	28	300
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type _____
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for _____
Water	Y/N	Y/N	Y/N	Y/N	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Jesus Romero		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		12/12	
Date:	Phone:		
	Witness:		