

HOBBS OCD

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

JUN 17 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron Midcontinent, LP	API Number 30-025-21866
Property Name Vacuum Glorieta West Unit	Well No 3

Surface Location

U.L. - Lat K	Section 24	Township 17S	Range 34E	Feet From 1880	N/S Line S	Feet From 1880	E/W Line W	County Lea
-----------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR INJ	PRODUCER OIL	DATE 4/10/19
------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A) Surf-Intern	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	28	57
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WIR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

0 Pressure on Surface Valve.

Signature:	OIL CONSERVATION DIVISION
Printed name: Jesus Romero	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Witness: