

HOBBS OCD

JUN 17 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-31835
Property Name Vacuum Glorieta West Unit	Well No. 9

2. Surface Location

U/L - Lot C	Section 25	Township 17S	Range 34E	Feet from 73	N/S Line N	Feet From 1411	E/W Line W	County Lea
----------------	---------------	-----------------	--------------	-----------------	---------------	-------------------	---------------	---------------


Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR (INJ)	PRODUCER OIL	DATE 3-27-19
------------------	----------------	-------------------	-----------------	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	458
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Jesus Roman	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness: 