

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 17 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron Midcontinent, LP		API Number 30-025-38140
Property Name New Mexico O State NCT-1		Well No. 040

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
J	36	17S	34E	1885	S	1978	E	Lea


Well Status

TAP'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☐ NO ☒	YES ☐ NO ☒	INJ ☐ SWD ☒	OIL ☐ GAS ☐	6-11-19

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csmg	(E)Tubing
Pressure	0	0		0	50
Flow Characteristics					
Puff	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	CO2 _____
Steady Flow	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	WTR _____
Surges	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	GAS _____
Down to nothing	Y ☐ N ☒	Y ☐ N ☐	Y ☐ N ☐	Y ☐ N ☒	If applicable type _____
Gas or Oil	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	fluid injected for _____
Water	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	Waterflood _____

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: 6-11-19	Phone:		
	Witness:		