

District I
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

HOBBS OCD

JUN 17 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-21637
Property Name Vacuum Glorieta West Unit	Well No 87

7. Surface Location

UL - Lot J	Section 36	Township 17S	Range 34E	Feet from 2090	N/S Line S	Feet From 2686	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------


Well Status

TA'D Well YES ☒	SHUT-IN YES ☒	INJECTOR INJ ☐ SWD ☐	PRODUCER ☒ OIL ☐ GAS	DATE 4-10-19
---	---	---	--	-----------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)P tubing
Pressure	0	0	N/A	35	170
Flow Characteristics					
Puff	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	CO2 ☐
Steady Flow	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	WTR ☒
Surges	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	GAS ☐
Down to nothing	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	If applicable type
Gas or Oil	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	fluid injected for
Water	☒ Y ☐ N	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Eloy Carmona	Entered into RBDMS
Title: FSR	Re-test
E-mail Address: ECarmona@Chevron.com	
Date: 4-10-19	
Phone: 575-200-6265	
Witness:	