

District I
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

HOBBS OCD

JUN 17 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-30126
Property Name Vacuum Glorieta West Unit	Well No 102



UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
P	36	17S	34E	990	S	990	E	Lea

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☒ NO	YES ☒ NO	INJ SWD	☒ OIL GAS	4-10-19

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	35	100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Eloy Carmona	Entered into RBDMS
Title: FSA	Re-test 
E-mail Address: E.Carmona@Chevron.com	
Date: 4-10-19	Phone: 575-200-4265
	Witness: