

JUN 17 2019

RECEIVED

BRADENHEAD TEST REPORT

Surface Location									
U.L. - Lat	Section	Township	Range		Feet from	N/S Line	Feet from	E/W Line	County
N	36	17S	34E		990	S	2310	W	Lea

TAYD Well		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	<u>NO</u>	YES	<u>NO</u>	INJ	SWD	<u>OIL</u>	GAS	4-19-19

	(A) Surf-Interm	(B) Inter(m)1	(C) Inter(m)2	(D) Prod Casing	(E) Tubing
Pressure	0	0	0	30	250
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	CO ₂ ☒
Steady Flow	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	WIR ☒
Surges	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	GeAS ☒
Down to nothing	☒ Y / N	☒ Y / N	☒ Y / N	Y / ☒ N	If applicable type
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	fluid injected for
Water	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	Waterflow

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION
Printed name: <i>Eloy Carmore</i>		Entered into RBDMS
Title: <i>FSA</i>		Re-test <i>7R</i>
E-mail Address: <i>ECarmore@Meridian.com</i>		
Date: <i>4-19-19</i>	Phone: <i>575-200-6265</i>	
Witness:		