

District I
1625 N. French Dr., Hobbs, NM 88240
Phone (505) 393-6161 Fax (505) 393-0720

HOBBS OCD
JUN 17 2019
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-31131
Property Name Vacuum Glorieta West Unit	Well No. 115 H

Surface Location

UL - Lot A	Section 1	Township 18 S	Range 34 E	Feet from 604	N/S Line N	Feet From 856	E/W Line E	County Lea
---------------	--------------	------------------	---------------	------------------	---------------	------------------	---------------	---------------



Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ SWD	PRODUCER ☒ OIL GAS	DATE 4-10-19
--	--	---------------------	--	-----------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod C'sng	(E) Tubing
Pressure	0	0	N/A	60	450
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N	Y/N	CO2 _____
Steady Flow	Y/N ☒	Y/N ☒	Y/N	Y/N	WTR ☒
Surges	Y/N ☒	Y/N ☒	Y/N	Y/N	GAS _____
Down to nothing	Y/N ☒	Y/N ☒	Y/N	Y/N	If applicable type
Gas or Oil	Y/N ☒	Y/N ☒	Y/N	Y/N	fluid injected for
Water	Y/N ☒	Y/N ☒	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Eloy Carmona	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: ECarmona@Chevron.com	
Date: 4-10-19	
Phone: 505-200-6265	
Witness:	