

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUN 17 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent, LP	API Number 30-025-23887
Property Name North Vacuum ABO West Unit	Well No 018

Surface Location

CL - Lot E	Section 27	Township 17S	Range 34E	Feet from 1980	N/S Line N	Feet From 1980	E/W Line W	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D Well YES	SHUT-IN YES	INJECTOR YES	PRODUCER OIL	DATE 7-14-19
------------------	----------------	-----------------	-----------------	-----------------

OBSERVED DATA

	(A) Surf-Intern	(B) Intern(1)	(C) Intern(2)	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	0	1250
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Christy</i>	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title:	Re-test
E-mail Address.	
Date:	Phone
	Witness