

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 11 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Chevron Midcontinent, LP</i>	API Number <i>30-025-02231</i>
Property Name <i>Central Vacuum Unit</i>	Well No. <i>52</i>

2. Surface Location

UL - Lot <i>B</i>	Section <i>36</i>	Township <i>17S</i>	Range <i>34E</i>	Feet from <i>660</i>	N/S Line <i>N</i>	Feet From <i>1980</i>	E/W Line <i>E</i>	County <i>Lea</i>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ SWD	PRODUCER ☒ OIL GAS	DATE <i>5/2/19</i>
--	--	---------------------	--	-----------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Cans	(E)Tubing
Pressure	<i>0</i>	<i>0</i>	<i>0</i>	<i>75</i>	<i>300</i>
Flow Characteristics					
Puff	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	CO2 _____
Steady Flow	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	WTR _____
Surges	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	GAS _____
Down to nothing	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	If applicable type
Gas or Oil	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	fluid injected for
Water	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Flowing Well - will but into replace packer or convert to rod pump

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: <i>Zach Wood</i>	Entered into RBDMS
Title: <i>PSS</i>	Re-test <i>[Signature]</i>
E-mail Address: <i>woodz@chevron.com</i>	
Date: <i>5-2-19</i>	Phone: <i>575-631-9475</i>
Witness:	