

District I
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 11 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Chevron Midcontinent, LP</i>	API Number <i>30-025-02324</i>
Property Name <i>Central Vacuum Unit</i>	Well No. <i>126</i>

1. Surface Location

UL - Lot <i>A</i>	Section <i>12</i>	Township <i>18S</i>	Range <i>34E</i>	Feet from <i>330</i>	N/S Line <i>N</i>	Feet From <i>990</i>	E/W Line <i>E</i>	County <i>LEA</i>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D Well ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☐ INJ ☐ SWD	PRODUCER ☒ OIL ☐ GAS	DATE <i>5-2-19</i>
--	--	---	--	-----------------------

OBSERVED DATA

	(A) Surf-Interm	(B) Interm(1)	(C) Interm(2)	(D) Prod Csmg	(E) Tubing
Pressure	<i>0</i>			<i>0</i>	<i>0</i>
Flow Characteristics					
Puff	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	CO2 _____
Steady Flow	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	WTR _____
Surges	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	GAS _____
Down to nothing	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	If applicable type
Gas or Oil	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	fluid injected for
Water	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: <i>Zach Wood</i>	Entered into RBDMS <i>[Signature]</i>
Title: <i>PSS</i>	Re-test
E-mail Address: <i>wood@chevron.com</i>	
Date: <i>5-2-19</i>	Phone: <i>575-631-9475</i>
Witness:	