

Printed
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 11 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron Midcontinent, LP	API Number 30-025-25733
Property Name Central Vacuum Unit	Well No. 93

Surface Location

UL - Lot M	Section 31	Township 17S	Range 35E	Feet From 10	N/S Line S	Feet From 1136	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	------------------------	----------------------	--------------------------	----------------------	----------------------


Well Status

TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ SWD	PRODUCER OIL GAS	DATE 5-2-19
--	--	--	---------------------	-----------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	0	0	2050
Flow Characteristics					
Puff	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	CO2 _____
Steady Flow	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	WTR _____
Surges	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	GAS _____
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	If applicable type
Gas or Oil	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	fluid injected for
Water	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	☒ Y ☒ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 5-2-19	Phone:
	Witness: