

HOBBS OCD

JUL 11 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
RECEIVED Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06410
Property Name North East Drinkard Unit (NEDU)		Well No. 106

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
C	3	21S	37E	660	N	1980	W	Leq

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	NO	YES	NO	INJ	SWD	OIL	GAS	1-31-19

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	$\emptyset$	$\emptyset$	N/A	$\emptyset$	900
Flow Characteristics					
Puff	$\emptyset$ / N	Y / $\emptyset$	Y / N	$\emptyset$ / N	CO2 —
Steady Flow	Y / $\emptyset$	Y / $\emptyset$	Y / N	Y / $\emptyset$	WTR ☒
Surges	Y / $\emptyset$	Y / $\emptyset$	Y / N	Y / $\emptyset$	GAS —
Down to nothing	$\emptyset$ / $\emptyset$	Y / $\emptyset$	Y / N	$\emptyset$ / N	Type of Fluid
Gas or Oil	Y / $\emptyset$	Y / $\emptyset$	Y / N	Y / $\emptyset$	Injected for
Water	Y / $\emptyset$	Y / $\emptyset$	Y / N	Y / $\emptyset$	Water flood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: 1-31-19	Phone: 575-441-5196	KF	
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM