

HOBBS OCD
JUL 11 2019
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06495	
Property Name North East Drinkard Unit (NEDU)		Well No. 110	

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
G	3	21S	37E	1980	N	1980	E	Lea

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 1-31-19
--	--	--	-----	-----	-----------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	$\emptyset$	N/A	N/A	$\emptyset$	1000
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Water level if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		XCJ	
Date: 1-31-19	Phone: 575-441-5196		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM