

HOBBS OCD

JUL 11 2019

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06509	
Property Name North East Drinkard Unit (NEDU)		Well No. 112	

Surface Location

UL - Lot A	Section 3	Township 21S	Range 37E	Feet from 660	N/S Line N	Feet From 660	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	PRODUCER OIL ☒ GAS	DATE 2-1-19
--	--	--	--	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	$\emptyset$	$\emptyset$	N/A	$\emptyset$	1050
Flow Characteristics					
Pull	☒ Y ☒ N	☒ Y ☒ N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	☒ Y ☒ N	☒ Y ☒ N	Y / N	Y / N	Type of fluid injected for water flow if applies
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		XJ	
Date: 2-1-19	Phone: 575-441-5196		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM