

HOBBS OCD

JUL 11 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
RECEIVED Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Oil Corp.		API Number 30-025-06519
Property Name North East Drinkard Unit (NEDU)		Well No. 207

1. Surface Location

UT. - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
14	3	21S	37E	2970	3	2308	W	Lea

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 3-5-19
------------------	-------------------------------------	----------------	-------------------------------------	---	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	Ø	Ø	-	Ø	1155
Flow Characteristics					
Puff	☒ Y ☐ N	☐ Y ☒ N	☐ Y ☐ N	☒ Y ☐ N	CO2 ☐
Steady Flow	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	WTR ☒
Surges	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	GAS ☐
Down to nothing	☒ Y ☐ N	☐ Y ☐ N	☐ Y ☐ N	☒ Y ☐ N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	
Water	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☐ N	☐ Y ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		X7	
Date: 3-5-19	Phone: 575-441-5196		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM