

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 11 2019

BRADENHEAD TEST REPORT

RECEIVED Apache Oil Corp.	Operator Name	API Number
	Property Name	Well No.
North East Drinkard Unit (NEDU)		309

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
Q	3	21S	37E	1830	S	660	E	Leq

Well Status

TA'D WELL	YES	SHUT-IN	YES	INJECTOR	SWD	OIL PRODUCER	GAS	DATE
	NO	NO	INT					4-11-19

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	—	—	Ø	1170
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	(Y) / N	CO2 —
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR ✓
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS —
Down to nothing	Y / N	Y / N	Y / N	(Y) / N	Type of Fluid
Gas or Oil	Y / (N)	Y / N	Y / N	(Y) / N	Injected for
Water	Y / (N)	Y / N	Y / N	(Y) / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole	OIL CONSERVATION DIVISION
Printed name: Tracy Cole	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 4-11-19	Witness:
Phone: 575-441-5196	

INSTRUCTIONS ON BACK OF THIS FORM