

State of New Mexico
Energy, Mining and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

RECEIVED
July 1, 2019

Company Name Apache Oil Corp.	API Number 30-025-06532
Property Name North East Drinkard Unit (NEDU)	Well No. 511

1. Surface Location									
UL - Lot M	Section 11	Township 21S	Range 37E		Feet From 660	N/S Line S	Feet From 660	E/W Line W	County Lea

Well Status						DATE
TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJECTOR SWD	OIL PRODUCER GAS	6-20-19

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	☒	☒	—	☒	1120
Flow Characteristics					
Puff	☒ N	☒ Y	Y / N	☒ Y	CO2 —
Steady Flow	☒ Y	☒ Y	Y / N	☒ Y	WTR ☒
Surges	☒ Y	☒ Y	Y / N	☒ Y	GAS —
Down to nothing	☒ Y	☒ Y	Y / N	☒ Y	Type of Fluid
Gas or Oil	☒ Y	☒ Y	Y / N	☒ Y	Injected for
Water	☒ Y	☒ Y	Y / N	☒ Y	Water flow if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Tracy Cole	OIL CONSERVATION DIVISION
Printed name: Tracy Cole	Entered into RBDMS
Title:	Re-test X
E-mail Address:	
Date: 6-20-19	
Phone: 575-441-5196	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM