

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 12 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28953
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 122

7. Surface Location

UL - Lot E	Section 29	Township 18-S	Range 38-E	Feet from 1660	N/S Line NORTH	Feet From 180	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status ACTIVE	SHUT-IN NO	PRODUCING YES	DATE 7-1-19
-----------------------	---------------	------------------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	10	NA	NA	32	1035
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Surface - puff of gas
Production Casing - Bleed down to zero in 30 seconds

Kelcee Elston 7-1-19

Signature:	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date:	Phone: 806-592-6280
Witness:	