

JUN 24 2019

RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28980
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 183

7. Surface Location

UL - Lot E	Section 5	Township 19N	Range 38-E	Feet from 2540	N/S Line NORTH	Feet From 1423	E/W Line WEST	County LEA
---------------	--------------	-----------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status <i>ACTIVE</i>	SHUT-IN <i>NO</i>	PRODUCING <i>YES</i>	DATE 06-01-19
------------------------------	----------------------	-------------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	10	NA	NA	330	385
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

*Timothy Lane* Long 06-01-19

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: JUN 18 2019	
Phone: 806-592-6280	
Witness:	