

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp.		API Number #30-025-20116	
Property Name McCallister St. 0005		Well No. #5	
Surface Location			
UL - Lot M	Section 25	Township 17S	Range 34E
Feet from 6600		N/S Line South	Feet from 560
E/W Line West		County Lea	
Well Status			
TA'D WELL YES NO	SHUT-IN YES NO	INJ INJECTOR	SWD OIL
PRODUCER GAS		DATE 7/12/19	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0	—	30	90
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Field
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if any.

HOBBS OCD
JUL 18 2019
RECEIVED

Signature: Cesar Rocha		OIL CONSERVATION DIVISION	
Printed name: Cesar Rocha		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: Cesar.Rocha@apachecorp.com.		X 7	
Date: 7-12-19	Phone: 575 942 9689		
Witness:			