

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 18 2019

BRADENHEAD TEST REPORT

Operator Name Apache Corporation		RECEIVED 30-025-37681
Property Name Southeast Lusk Fed		
		Well No. 6

Surface Location

UL - Lot A	Section	Township 19S	Range 32E	Feet from 990	N/S Line FNL	Feet From 990	E/W Line FEL	County Lea
----------------------	---------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

YES TA'D WELL (NO)	YES SHUT-IN (NO)	INJ INJECTOR (SWI)	OIL PRODUCER	GAS	DATE 7/12/19
---------------------------	-------------------------	---------------------------	--------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	—	0	1526
Flow Characteristics					
Puff	(Y) N	(Y) N	Y / N	Y / N	CO2 —
Steady Flow	Y / (N)	Y / (N)	Y / N	Y / N	WTR —
Surges	Y / (N)	Y / (N)	Y / N	Y / N	GAS —
Down to nothing	(Y) N	(Y) N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / N	Injected for
Water	Y / (N)	Y / (N)	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Cesar Rocha		OIL CONSERVATION DIVISION	
Printed name: Cesar Rocha		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: Cesar.Rocha@apache corp. com		7C 7	
Date: 7-12-19	Phone: 575 942 9689		
Witness:			