

HOBBS OCD

JUL 24 2019

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		API Number 3002537513 0000	
Property Name EDITH BUTLER		Well No. 4	

1. Surface Location

UT. - Lot I	Section 13	Township 22S	Range 37E	Feet from 1980	NS Line ☒	Feet from 850	EW Line ☒	County LEA
-----------------------	----------------------	------------------------	---------------------	--------------------------	--	-------------------------	--	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ ☐	INJECTOR SWD ☒	PRODUCER GAS ☐	DATE 7/2/19
---	---	---------------------------------	---	--	-----------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	45	100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pearson		OIL CONSERVATION DIVISION	
Printed name: CHAD PIERSON		Entered into RBDMS	
Title:		Re-test X	
E-mail Address:			
Date:	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM