

HOBBS OCD

JUL 24 2019

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ADACHE CORPORATION		*API Number 30025702730000
Property Name E.W. WARDEN		Well No. 5

1. Surface Location

UT. - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
L	15	223	37E	1880	S	660	W	LEA

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ	INJECTOR SWD ☒ OIL	PRODUCER GAS	DATE 6/25/2019
--	--	-----	--	-----------------	--------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	35	150
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected or water level if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pierson		OIL CONSERVATION DIVISION	
Printed name: CHAD PIERSON		Entered into RBDMS	
Title:		Re-test 27	
E-mail Address:			
Date:	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM