

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name APACHE CORP				API Number 300250-9035				
Property Name SOUTH EDWILE SEVEN RIVERS QUEEN				Well No. 504				
2. Surface Location								
UL - Lot K	Section 22	Township 22S	Range 36E	Feet from 1980	NS Line NO	Feet From 1650	EW Line NO	County LEA

Well Status

TA'D WELL ☒ YES ☐ NO	SHUT-IN ☒ YES ☐ NO	INJECTOR ☒ INJ ☐ SWD	PRODUCER ☐ OIL ☐ GAS	DATE 7/18/19
--	--	--	---	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	-	-	0	0
Flow Characteristics					TA
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for water level if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pearson		OIL CONSERVATION DIVISION	
Printed name: CHAD PIERSON		Entered into RBDMS	
Title:		Re-test XJ	
E-mail Address:			
Date:	Phone:		
	Witness:		

INSTRUCTIONS ON BACK OF THIS FORM