

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 24 2019

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		300' RECEIVED 9178 Well No. 415
Property Name SOUTH EVNICE SEVEN RIVERS QUEEN		

1. Surface Location

UL - Lot J	Section 36	Township 22S	Range 36E	Feet from 1650	N/E Line 0	Feet from 2310	N/E Line 0	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	PRODUCER OIL	GAS	DATE 7/18/19
--	--	--	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	0	650
Flow Characteristics					
Pull	☒ N	Y / N	Y / N	☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☐
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	☒ N	Y / N	Y / N	☒ N	Type of fluid injected for water flood if applies.
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pearson		OIL CONSERVATION DIVISION
Printed name: CHAD PEARSON		Entered into RBDMS
Title:		Re-test: 27
E-mail Address:		
Date:	Phone:	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM