

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 24 2019

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		RECEIVED 3002570252 Well No. 1
Property Name EDITH BUTLER B		


1. Surface Location									
UT. - Lot I	Section 13	Township 22S	Range 37E		Feet from 1980	N/E Line N/E	Feet from 660	W Line W	County LFA

Well Status						DATE		
TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR NO	PRODUCER OIL	GAS	7/18/19

OBSERVED DATA

	(A) Surface	(B) Interim(1)	(C) Interim(2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	45	100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 — WTR — GAS — Type of Fluid Injected for Waterflood if applies.
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pierson		OIL CONSERVATION DIVISION
Printed name: CHAD PIERSON		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM