

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name APACHE CORP		Well Number 380 253 1158 0000
Property Name McDonald AC 1 #		Well No. 32

1. Surface Location

UT. - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
I	16	22S	36E	1340	S	1240	E	LEA

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	PRODUCER OIL ☐ GAS	DATE 6/25/2019
--	--	--	---	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	—	—	0	350
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pierson		OIL CONSERVATION DIVISION
Printed name: CHAD PIERSON		Entered into RBDMS
Title:		Rc-test
E-mail Address:		7/7
Date:	Phone:	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM