

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 24 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name APACHE CORP		AP# Number 3002570392
Property Name EUGENE WOODS		Well No. 7

1. Surface Location

UT. - Lot A	Section 22	Township 22S	Range 37E	Feet from 732	NS Line 0	Feet From 641	EW Line 0	County LEA
-----------------------	----------------------	------------------------	---------------------	-------------------------	---------------------	-------------------------	---------------------	----------------------

Well Status

TA'D WELL YES	NO 0	YES 0	SHUT-IN NO	INJ	INJECTOR SWD	PRODUCER 0	GAS	DATE 7/8/19
------------------	-------------	--------------	---------------	-----	-----------------	----------------------	-----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	0	—	—	45	0
Flow Characteristics					
Puff	Y/N 0	Y/N	Y/N	Y/N 0	CO2 —
Steady Flow	Y/N 0	Y/N	Y/N	Y/N 0	WTR —
Surges	Y/N 0	Y/N	Y/N	Y/N 0	GAS —
Down to nothing	Y/N 0	Y/N	Y/N	Y/N 0	Type of fluid injected for water level if applies.
Gas or Oil	Y/N 0	Y/N	Y/N	Y/N 0	
Water	Y/N 0	Y/N	Y/N	Y/N 0	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: CHAD PIERSON		OIL CONSERVATION DIVISION
Printed name: CHAD PIERSON		Entered into RBDMS
Title:		Re-test XJ
E-mail Address:		
Date:	Phone:	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM