

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 24 2019

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		RECEIVED 2082538798
Property Name STATE PA		
		Well No. 6

1. Surface Location

UT. - Lot B	Section 17	Township 22S	Range 37E	Feet from 990	Line 1850	Line 1850	County LEA
-----------------------	----------------------	------------------------	---------------------	-------------------------	---------------------	---------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ	INJECTOR SWD ☒ OIL	PRODUCER GAS	DATE 7/9/19
--	--	-----	--	-----------------	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	—	—	45	110
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pierson		OIL CONSERVATION DIVISION
Printed name: CHAD PIERSON		Entered into RBDMS
Title:		Re-test XJ
E-mail Address:		
Date:	Phone:	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM