

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 24 2019

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		*API No. 3002538812	
Property Name EUGENE WOODS		Well No. 12	

Surface Location

UT. - Lot B	Section 22	Township 22S	Range 37E	Feet from 750	Line 2	Feet from 1725	Line 2	County LEA
-----------------------	----------------------	------------------------	---------------------	-------------------------	------------------	--------------------------	------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ	INJECTOR SWD ☒ OIL	PRODUCER GAS	DATE 7/8/19
--	--	-----	--	-----------------	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	45	110
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Dierson		OIL CONSERVATION DIVISION	
Printed name: CHAD DIERSON		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM