

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCT

JUL 24 2019

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		30025101120000	
Property Name JL. MURPHY		Well No. 3	

1. Surface Location

UT. - Lot N	Section 24	Township 22S	Range 37E	Feet From 350	N/S Line S	Feet From 1720	E/W Line W	County LEA
-----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒	SHUT-IN YES ☒	INJECTOR INJ ☐	SWD ☐	PRODUCER ☒ OIL ☐ GAS	DATE 7/2/19
---	---	---------------------------------------	---------------------------	--	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	Ø	-	-	35	150
Flow Characteristics					
Pull	Ø / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Ø / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pearson		OIL CONSERVATION DIVISION	
Printed name: CHAD PIERSON		Entered into RBDMS	
Title:		Re-Inst X7	
E-mail Address:			
Date:	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM