

HOBBS OCD

JUL 24 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		*API Number 3002570765 0000	
Property Name NM BZ ST NCT. 8		Well No. 7	

1. Surface Location

UT. - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
N	16	23S	37E	1980	N	660	E	LEA

Well Status

☒ YES TA'D WELL	☒ YES SHUT-IN	☒ YES INJECTOR	☐ SWD	☐ OIL PRODUCER	☐ GAS	DATE 7/2/19
---	---	--	------------------------------	---------------------------------------	------------------------------	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	0	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Chad Pierson		OIL CONSERVATION DIVISION	
Printed name: CHAD PIERSON		Entered into RBDMS	
Title:		Re-test	
E-mail Address:		X7	
Date:	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM