

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Apache Corp</i>	* API Number <i>30025-09752</i>
Property Name <i>NUGSAU</i>	Well No. <i>013 (1013)</i>

2. Surface Location

UL - Lot <i>N</i>	Section <i>30</i>	Township <i>19S</i>	Range <i>37E</i>	Feet from <i>330</i>	N/S Line <i>S</i>	Feet from <i>330</i>	E/W Line <i>W</i>	County <i>Lea</i>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER	GAS	DATE <i>7/25/19</i>
--	--	--	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interim(1)	(C) Interim(2)	(D) Prod Casing	(E) Tubing
Pressure	0		0	0	700
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected Or
Water	Y / N	Y / N	Y / N	Y / N	Waterflood If
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Doug Mathews</i>	OIL CONSERVATION DIVISION
Printed name: <i>Doug Mathews</i>	Entered into RBDMS
Title: <i>Pumper III</i>	Re-test
E-mail Address: <i>doug.mathews@apachecorp.com</i>	
Date: <i>7/25/19</i>	Phone: <i>505-631-7713</i>
Witness:	