

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 24 2019

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		Well No. 300258864 24864	
Property Name ELLIOTT B17		Well No. 2	


Surface Location									
UT. - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County	
A	17	22S	37E	330	N	330	E	LEA	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 7/8/19	

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	35	120
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ___ WTR ___ GAS ___ Type of fluid Injected for Waterflood if applies
Steady flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: CHAD PIERSON		Entered into RBDMS	
Title:		Re-test 27	
E-mail Address:			
Date:	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM