Date: 07/22/2019

Phone: 432-661-1364

Witness:

HOBBS OCD

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

JUL 3 0 2019

BRADENHEAD TEST REPORT

b	C	E	I۱	1	F	Г
ĸ	•		9	•	L	_

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating								30-025-10629				,
Property Name SKELLY PENROSE B UNIT								Well No.			Vell No.	
		•			7. Surface Loca	tion			L			
UL - Lot B	Section 5	Township 23S	Range 37E		Feet from 660		S Line ORTH	Feet From		E/W Line EAST	County LEA	
				<u> </u>	Well Statu	ıs			l l		-	
Ta' D Well		shut-in No		INJECTOR Inj		PRODUCING		3	DATE 07/14/2019			
1	No OPF	N RRADEN		FERMED	IATE TO ATMOSPH	FRE INDI	L	Y FOR 15 N	MINUTES	 S EACH		
	OLE	IN DRADEN	ILAD AND IN	ERVIED	OBSERVED D		TIDOADL	71 FOR 15 I	MICIA	LACII		
If bradenhead	flowed wa		l of the description		pply:							
		(A)Si	(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure			<u>0#</u>						0#	ŧ	490#	$\overline{}$
Flow Charac												
Puff			Y		Y/N		Y / N		Y] /	
Steady Flow			N	Y / N			Y/N		N		<u>wtr</u>	
Surge			N	Y / N .			Y/ N		N			
Down to nothing			Y Instant	ļ	Y/N		Y/N			Y	_	
Gas or Oil Water			N	ļ	Y/N Y/N		Y/N Y/N		N N		_	
·····				<u> </u>							╛	
If bradenhead	flowed wa	ter, check al	l of the description	ons that a	pply:							
CLEAR		FRE	SH		SALTY SUI		SULFU	CFUR		BLACK		
	_,	l					1					
Remarks:												
		•										
					•							
Signature:								OIL CONSERVATION DIVISION				
Printed name: C. DALE KELTON							Entered into RBDMS					
Title: PRESIDENT							Re-test			/ 		
		nceenerou@	suddenlink net							-/	/	 · -
E-mail Address: providenceenergy@suddenlink.net										,		