

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 30 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating	API Number 30-025-10631
Property Name SKELLY PENROSE B UNIT	Well No. 27

7. Surface Location

UL - Lot F	Section 5	Township 23S	Range 37E	Feet from 1980	N/S Line NORTH	Feet From 1980	E/W Line WEST	County LEA
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Ta' D Well No	SHUT-IN No	INJECTOR Inj	PRODUCING	DATE 07/14/2019
------------------	---------------	-----------------	-----------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0#			40	465
Flow Characteristics					
Puff	Y	Y / N	Y / N	Y	
Steady Flow	N	Y / N	Y / N	N	
Surges	N	Y / N	Y / N	N	
Down to nothing	Y 2 Seconds	Y / N	Y / N	Y	
Gas or Oil	N	Y / N	Y / N	N	
Water	N	Y / N	Y / N	N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Casing pressure bled down in 2 seconds with light clear fluid mist.

Signature: 	OIL CONSERVATION DIVISION
Printed name: C. DALE KELTON	Entered into RBDMS
Title: PRESIDENT	Re-test
E-mail Address: providenceenergy@suddenlink.net	
Date: 07/22/2019	
Phone: 432-661-1364	
Witness:	