

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

JUL 30 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating	API Number 30-025-10632
Property Name SKELLY PENROSE B UNIT	Well No. 20

7. Surface Location

UL - Lot C	Section 5	Township 23S	Range 37E	Feet from 330	N/S Line NORTH	Feet From 2310	E/W Line WEST	County LEA
---------------	--------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Ta' D Well No	SHUT-IN No	INJECTOR	PRODUCING Oil	DATE 07/13/2019	Well St No
------------------	---------------	----------	------------------	--------------------	---------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	N/A			35	35
Flow Characteristics					
Puff	N	Y / N	Y / N	Y / N	
Steady Flow	N	Y / N	Y / N	Y - N	
Surges	N	Y / N	Y / N	Y - N	
Down to nothing	N	Y / N	Y / N	Y / N	
Gas or Oil	N	Y / N	Y / N	Y / N	
Water	N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Cemented to Surface

Signature: 	OIL CONSERVATION DIVISION
Printed name: C. DALE KELTON	Entered into RBDMS
Title: PRESIDENT	Re-test 
E-mail Address: providenceenergy@suddenlink.net	
Date: 07/22/2019	Phone: 432-661-1364
Witness:	