

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

JUL 30 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating	API Number 30-025-32113
Property Name SKELLY PENROSE B UNIT	Well No. 72

7. Surface Location

UL - Lot B	Section 5	Township 23S	Range 37E	Feet from 1220	N/S Line NORTH	Feet From 1370	E/W Line EAST	County LEA
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Ta' D Well No	SHUT-IN No	INJECTOR	PRODUCING Oil	DATE 07/13/2019
------------------	---------------	----------	------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:



	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0			40	40
Flow Characteristics					
Puff	N	Y / N	Y / N	Y / N	
Steady Flow	N	Y / N	Y / N	Y - N	
Surges	N	Y / N	Y / N	Y - N	
Down to nothing	Y	Y / N	Y / N	Y / N	
Gas or Oil	N	Y / N	Y / N	Y / N	
Water	N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Cemented to the surface.

Signature: 	OIL CONSERVATION DIVISION
Printed name: C. DALE KELTON	Entered into RBDMS
Title: PRESIDENT	Re-test
E-mail Address: providenceenergy@suddenlink.net	
Date: 07/22/2019	
Phone: 432-661-1364	
Witness:	