State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Operator Name Property Name NORTH HORRS (G/SA) LINIT										³ API Number 30-025-34964			
Property Name NORTH HOBBS (G/SA) UNIT											Well No. 541		
		 -			7. Surface Locat	ion							
		Township	, l		Feet from		N/S Line Fee		From	E/W Line	County LEA		
A 32 18-S		18-S	38-E		887 Well Status				86	6 EAST L			
Well Status		(SHUT-IN		PRODUCING		5-30 L9		[‡] Dra		ducer		
		N BRADENH	EAD AND INT	ERMEDI	ATE TO ATMOSPHI	ERE INDI			5 MINUT				
				_	OBSERVED DA	TA							
If bradenhead	l flowed wa		of the description	_	ply: rm(1)-Interm(2)	Clinte	rm-Prod		(D)Pro	od Csng	(E)Tubing		
Pressure			5										
Flow Characteristics)	<u> </u>	NA	101				185	500			
Puff /		7	(¹)(6)		Y/N		Y/N		Y/N		-		
Steady Flow			Y / 🛇		Y / N		Y/N		Y/N		┪		
Surges			Y/\$		Y/N		Y / N		Y / N				
Down to nothing Gas or Oil			(Y) / N		Y/N		Y/N			Y/N			
Water			Y/(N		Y/N Y/N		Y/N		Y/N Y/N		_		
If bradenhead	l flowed wa	FRES	of the descriptio	ns that ap	SALTY		SULFU	R		BLACK			
Remarks:						INJEC	CTING AT	THIS TI	ME	WTR,GA	S,CO2		
Signature: Printed name: MENDY JOHNSON								OIL CONSERVATION DIVISION Entered into RBDMS					
Title: ADMINISTRATIVE ASSOCIATE								Re-test					
E-mail Addr	ess: mendy	johnson@ox	y.com	<u>om</u>									
Date:			Phone: 806-592-6280										
			Witness:							$ \wedge$			