

RECEIVED

Submit One Copy To Appropriate District Office

JUL 22 2019

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources

Revised November 3, 2011

District I 1625 N. French Dr., Hobbs, NM 88240
District II 811 S. First St., Artesia, NM 88210
District III 1000 Rio Brazos Rd., Aztec, NM 87410
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

DISTRICT-ARTESIA-OCD

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-61986
5. Indicate Type of Lease STATE [] FEE [X]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Spool SU
8. Well Number 2
9. OGRID Number 7377
10. Pool name or Wildcat Pecos Slope; Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: [] Oil Well [] Gas Well [X] Other P&A
2. Name of Operator EOG Resources, Inc.
3. Address of Operator 104 South Fourth Street, Artesia, NM 88210

4. Well Location
Unit Letter D 660 feet from the North line and 660 feet from the West line
Section 23 Township 7S Range 25E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,704' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS [] P AND A []
CASING/CEMENT JOB []
OTHER: [] [X] Location is ready for OCD inspection after P&A

- [X] All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
[X] Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
[X] A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- [X] The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Buried plastic liner removed.
[X] Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
[X] If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. 1" poly flow line is active, being used by surface owner (see attached).
[X] All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) Riser is part of active IACX/Roswell system.
[X] All other environmental concerns have been addressed as per OCD rules.
[X] Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. No, active pipeline(s) within YPC gas system.
[X] If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE [Signature] TITLE: Environmental Supervisor DATE 7/22/2019
TYPE OR PRINT NAME: Robert Asher E-MAIL: robert_asher@eogresources.com PHONE: 575-748-1471
For State Use Only

APPROVED BY: [Signature] TITLE: STAFF Mgr. DATE 7/26/19
Conditions of Approval (if any):

Bob Asher

From: Robert Smyzenski <robertsmyzenski@iacxroswell.com>
Sent: Monday, July 22, 2019 9:35 AM
To: Bob Asher
Subject: RE: Riser removal (Spool SU #2)

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hello Bob, the piping on this location is part of an active line in our system, I think that it would be part of our pipeline ROW. It would involve a lot of work and could be used in the future for some other purpose. Hopefully this is of some help to you. Please let me know if you need anything else.
Thanks for your help

Robert Smyzenski

Measurement Supervisor



robertsmyzenski@iacxroswell.com | www.iacx.com
6263 North Main St.
Roswell, NM 88201
Cell: 575-626-3256
Office: 575-363-3144

From: Bob Asher [mailto:Bob_Asher@eogresources.com]
Sent: Tuesday, July 16, 2019 6:39 AM
To: Robert Smyzenski <robertsmyzenski@iacxroswell.com>
Subject: Riser removal (Spool SU #2)

Robert,

I have another gas riser I need removed please. It is across the access road, south of the location.


Spool SU #2
33.698431; -104.377709
Section 23, T7S-R25E
Chaves County, New Mexico

If you have any questions please contact me. When the work is completed please inform me so I can relay that to the NMOCD.

Thank you,

Robert C. "Bob" Asher
Environmental Supervisor

Safety & Environmental Department
EOG Resources, Inc.
Artesia Division
EOG Safety Begins With YOUR Safety



- [Account Search](#)
- [Help?](#)
- [Treasurer Web](#)
- [Logout Public](#)

Account: R012798

*** Tax Rate does not include the Pecos Valley Artesian Conservancy District**

Location	Owner Information	Assessment History				
Parcel Number 4-144-041-289-458-000000	Owner Name D & M NM RANCHERS #2, LLC	Actual Value (2019 - Residential Cap applied)		\$202,777		
Tax Area 11N_8_10 - 11N-FC-CSW	In Care Of Name DONALD R HORTON	Primary Taxable		\$67,591		
Situs Address 1058 RED BLUFF RD	Owner Address 1501 ALTA DR FORT WORTH, TX 76107 USA	Tax Area: 11N_8_10		Tax Rate: 0.023157		
Legal Summary S: 1 T: 7S R: 25E NE4 - S2 S: 2 T: 7S R: 25E ALL S: 5 T: 7S R: 25E W2 S: 6 T: 7S R: 25E ALL S: 7 T: 7S R: 25E ALL S: 8 T: 7S R: 25E ALL S: 9 T: 7S R: 25E N2 - N2SW4 S: 11 T: 7S R: 25E E2E2 S: 12 T: 7S R: 25E ALL S: 13 T: 7S R: 25E ALL S: 14 T: 7S R: 25E ALL LESS N2N2 S: 17 T: 7S R: 25E ALL S: 18 T: 7S R: 25E ALL LESS N2NW4 S: 21 T: 7S R: 25E E2 S: 22 T: 7S R: 25E E2SW4 - S2SE4 - NE4SE4 S: 23 T: 7S R: 25E ALL S: 24 T: 7S R: 25E N2 - SW4 - W2SE4 S: 25 T: 7S R: 25E SW4 S: 26 T: 7S R: 25E S2 S: 27 T: 7S R: 25E N2NE4 - NE4NW4 - E2SE4 S: 32 T: 7S R: 25E ALL S: 35 T: 7S R: 25E NW4 10,156.48 ACRES, BK 739 PG 1735 QCD	Type	Actual	Assessed Acres	SQFT		
		Agriculture Land	\$31,990	\$10,663	10155.480	0.000
		Non-Residential Improvement	\$36,109	\$12,036		11613.000
		Tax Area: 11R_8_10		Tax Rate: 0.018005		
		Type	Actual	Assessed Acres	SQFT	
		Residential Land	\$8,200	\$2,733	1.000	0.000
		Residential Improvement	\$126,478	\$42,159		2029.000

Images

Tax Year	Taxes	
*2019	\$1,604.28	• Map
2018	\$1,584.24	• Sketch
		• GIS

* Estimated

Focusing On: 1058 RED BLUFF RD ROSWELL 88201