

AUG 09 2019

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp		API Number 30025064810000	
Property Name EAST BLINE bry		Well No. 20	

1 Surface Location									
UL Lat I	Section 11	Township 21	Range 37		Feet from 1980	N/S Line S	Feet From 330	E/W Line E	County Lea

Well Status									
YES	TA'D WELL ☒	YES	SHUT-IN ☒	☒	INJECTOR	SWD	OIL	PRODUCER	GAS
									DATE 7/10/19

OBSERVED DATA

	(A) Surface	(B) Intermit 1	(C) Intermit 2	(D) Prod Casing	(E) Tubing
Pressure	2			2	1789
Flow Characteristics					
Pull	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	CO2 ☐
Steady Flow	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	WTR ☒
Surges	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	GAS ☐
Down to nothing	☒ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☒ Y / ☐ N	Type of fluid Injected for Wellbore if applies
Gas or Oil	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	
Water	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	☐ Y / ☐ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Albert Rodriguez		OIL CONSERVATION DIVISION	
Printed name: ALBERT RODRIGUEZ		Entered into RBDMS	
Title: MECHANIC		Re-test	
E-mail Address:		X7	
Date: 7/10/19	Phone: 432-425 2963		
Witness:			