

AUG 09 2019

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp.		API Number 30025065460000	
Property Name EAST Blinebry Drinkard Unit		Well No. 36	

1. Surface Location

UL - Lot E	Section 12	Township 21	Range 37	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County LEA
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ ☒	SWD	OIL	PRODUCER	GAS	DATE 1/29/19
--	--	--------------------------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	Q	35		Q	1859
Flow Characteristics					
Pull	Y / N	☒ N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	☒ N	☒ N	Y / N	☒ N	Type of Fluid Injected for Well Seal & applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Albert Rodriguez		OIL CONSERVATION DIVISION	
Printed name: ALBERT Rodriguez		Entered into RBDMS	
Title: Mechanic		Re-test X	
E-mail Address:			
Date: 1/29/19	Phone: 432-425-2963		
Witness:			