

District I
1425 N. E.
P.O. Box 104 Rm 140
Albuquerque, NM 87104
Phone (505) 397-0720

HOBBS OCD
AUG 09 2019
RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Apache Corp		API Number 30025290610000	
Property Name EAST Bline by DRINKARD Unit		Well No. 57	

1. Surface Location									
UL - Lot 5	Section 1	Township 21	Range 37		Feet from 1650	N/S Line S	Feet From 1650	E/W Line W	County LEA

Well Status									
TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 2-11-19			

OBSERVED DATA

	(A) Surface	(B) Interm (1)	(C) Interm (2)	(D) Prod Casing	(E) Tubing
Pressure	2			90	1836
Flow Characteristics					
Pwf	Y / N	Y / N	Y / N	☒ N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ N	Type of Fluid Indicated for 1 Year and if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Albert Rodriguez		OIL CONSERVATION DIVISION	
Printed name: ALBERT Rodriguez		Entered into RBDMS	
Title: Mechanic		Re-test X7	
E-mail Address:			
Date: 2-11-19	Phone: 432-425-2963		
Witness:			