

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD
AUG 22 2019
RECEIVED

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING LP		* APT Number 30-025-03197	
Property Name NORTHEAST PEARL QUEEN UNIT		Well No. 8	

1 Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet From	E/W Line	County
B	23	19	35	330	N	2310	E	Lea

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR (INJ)	SWD	PRODUCER OIL	GAS	DATE 8-20-19
------------------	----------------	-------------------	-----	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interval (1)	(C) Interval (2)	(D) Prod Casing	(E) Testing
Pressure	0	0	N/A	0	1500
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddie Trujillo</i>		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness: <i>Kerry Fortner - OCD</i>			

399-3221

INSTRUCTIONS ON BACK OF THIS FORM