

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

AUG 22 2019

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING LP		30-025-03200
Property Name NORTHEAST PEARL QUEEN UNIT		Well No. 20

Surface Location

UL - Lot J	Section 23	Township 19	Range 35	Feet from 1980	NS Line S	Feet from 2180	E/W Line E	County Lea
---------------	---------------	----------------	-------------	-------------------	--------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR IN	SWD	PRODUCER OIL	GAS	DATE 8-20-19
------------------	----------------	----------------	-----	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interval	(C) Chatter	(D) Prod Cons	(E) Testing
Pressure	0	0	N/A	0	1500
Flow Characteristics					
Full	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Eddie Trujillo</i>	OIL CONSERVATION DIVISION
Printed name: Eddie Trujillo	Entered into RBDMS
Title: Leadman	Re-test
E-mail Address: eddie.trujillo@mavresources.com	
Date:	Phone: 575-399-3329
Witness: <i>Kerry Fortner - OCD</i>	

399-3221

INSTRUCTIONS ON BACK OF THIS FORM