

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 22 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name BREITBURN OPERATING LP		AP# Number 30-025-08604	
Property Name CONE JALMAT YATES POOL UNIT			Well No. 103

Surface Location

UL - Lot K	Section 13	Township 22S	Range 35E	Feet from 1980	NS Line S	Feet from 1980	E/W Line W	County Lea
---------------	---------------	-----------------	--------------	-------------------	--------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR NO	SWD NO	OIL PRODUCER	GAS DATE 8-19-19
------------------	----------------	----------------	-----------	-----------------	------------------------

OBSERVED DATA

	(A) Surface	(B) Intermediate	(C) Intermediate	(D) Red Clay	(E) Other
Pressure	0	0	14/17	0	275
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

MIT

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness: [Signature]			

INSTRUCTIONS ON BACK OF THIS FORM