

HOBBS OCD

AUG 22 2019

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name BREITBURN OPERATING LP		API Number 30-025-08640	
Property Name CONE JALMAT YATES POOL UNIT		Well No. 502	

¹ Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet from	E/W Line	County
L	24	22S	35 E	2310	S	990	W	Lea

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	PRODUCER OIL	GAS	DATE 8-20-19
--	--	--	-----	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interval (1)	(C) Interval (2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	NA	0	200
Flow Characteristics					
Full	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	CO2
Steady Flow	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	WTR
Surges	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	GAS
Down to nothing	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	Type of fluid injected for water flood if applies.
Gas or Oil	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	
Water	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-399-3329		
Witness:	<i>Ray Coleman</i>		

INSTRUCTIONS ON BACK OF THIS FORM