

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 22 2019

RECEIVED

BRADENHEAD TEST REPORT

Operator Name BREITBURN OPERATING LP		API Number 30-025-08651
Property Name CONE JALMAT YATES POOL UNIT		Well No. 602

2 Surface Location

UL - Lot J	Section 24	Township 22S	Range 35E	Feet from 1980	NS Line S	Feet from 1980	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	-------------------	--------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 8-20-19
--	--	--	-----	-----	-----------------	-----------------

OBSERVED DATA

	(A) Surface	(B) Intermediate	(C) Casinghead	(D) Production Casing	(E) Tubing
Pressure	0	0	N/A	0	200
Flow Characteristics					
Full	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Indicated for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo		Entered into RBDMS	
Title: Leadman		Re-test	
E-mail Address: eddie.trujillo@mavresources.com			
Date:	Phone: 575-899-3329		
Witness: <i>[Signature]</i>			

INSTRUCTIONS ON BACK OF THIS FORM