

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

AUG 22 2019

BRADENHEAD TEST REPORT

RECEIVED

Operator Name BREITBURN OPERATING LP	API Number 30-025-08663
Property Name CONE JALMAT YATES POOL UNIT	Well No. 701

1 Surface Location

UL - Lot H	Section 25	Township 22S	Range 35E	Feet from 1980	N/S Line N	Feet from 660	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	-------------------	---------------	------------------	---------------	---------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER GAS	DATE 8-20-19
--	--	--	-----	-----	-----------------	-----------------

OBSERVED DATA

	(A) Surface	(B) Intermediate	(C) Chokepoint	(D) Free Case	(E) Tubing
Pressure	0	0	NA	0	450
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	OIL CONSERVATION DIVISION	
Printed name: Eddie Trujillo	Entered into RBDMS	
Title: Leadman	Re-test	
E-mail Address: eddie.trujillo@mavresources.com		
Date:	Phone: 575-399-3329	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM